ATTACHMENT C SECURITY

Waste Isolation Pilot Plant Hazardous Waste Permit October 16, 2006

(This page intentionally blank)

ATTACHMENT C

SECURITY

TABLE OF CONTENTS

| Introduction | | | | <u>C-1</u> |
|------------------------------------|---------------|--------------|------|----------------|
| C-1 Security | | | | <u>C-1</u> |
| C-1a Security Procedures and Equip | <u>ment</u> | | | <u>C-1</u> |
| C-1a(1) 24-Hour Surveillance | System | | | <u>C-1</u> |
| C-1a(2) Barrier and Means to | Control Enti | <u>ry</u> | | <u>C-2</u> |
| C-1a(2)(a) <u>Barrier</u> | | - | | C-2 |
| C-1a(2)(b) Means to (| Control Entry | | | C-2 |
| C-1a(3) Warning Signs | | | | C-3 |

Waste Isolation Pilot Plant Hazardous Waste Permit October 16, 2006

(This page intentionally blank)

ATTACHMENT C

SECURITY

| I | Intr | odu | iction |
|---|------|-----|--------|
| | | | |

- This Permit Attachment describes the security measures taken at the Waste Isolation Pilot Plant
- 3 (WIPP) during the Disposal Phase. It describes the security equipment and procedures in place
- at the WIPP facility that continuously monitor and control entry onto the active portion¹ of the
- facility, including 24-hour security surveillance, fencing, and signs.
- 6 C-1 Security
- 7 The security requirements contained in Title 20 of the New Mexico Administrative Code,
- 8 Chapter 4, Part 1 (20.4.1.500 NMAC (incorporating 40 CFR §264.14)), and in 20.4.1.900 NMAC
- 9 (incorporating 40 CFR §270.14(b)(4)), require that security be provided by 24-hour surveillance
- or that a barrier be provided to control entry to the active portion of the facility at all times.
- 11 C-1a <u>Security Procedures and Equipment</u>
- The WIPP facility has been designed and will be operated to fully meet the security
- requirements contained in 20.4.1.500 NMAC (incorporating 40 CFR §264.14(b) and (c)). The
- WIPP facility has 24-hour security surveillance and the means to control entry to the active
- portion of the facility. In addition, warning signs are provided. These security requirements are
- 16 discussed below.
- 17 C-1a(1) <u>24-Hour Surveillance System</u>
- The WIPP facility's 24-hour surveillance system is comprised of security officers that provide
- protection 24 hours per day, 365 days per year. Security officers work to written procedures that
- 20 require visitors, contractors, and vendors to log in before they are allowed to proceed to the
- Main Gate for access into the Property Protection Area (PPA) and require continuous
- monitoring of the active portion of the facility. This system will be maintained to fulfill the
- requirements of 20.4.1.500 NMAC (incorporating 40 CFR §264.14(b)(1)).
- The major duties of the security officers are to control personnel, vehicle, and material
- 25 access/egress 24 hours per day, 365 days per year. During non-operational hours, the security
- officers conduct documented security patrols outside of the PPA, at a minimum rate of two per

¹ The active portion of the facility is the Property Protection Area (**PPA**) as described in Permit Module III. Within this area, the only area where transuranic (**TRU**) mixed wastes are handled outside of the Contact-Handled or Remote-Handled Packaging is inside the Waste Handling Building (**WHB**), the waste hoist, and the underground. Whenever TRU mixed waste is handled, a Controlled Area (**CA**) is established, for the purpose of radiation protection, which limits access to only trained personnel or to untrained personnel (visitors) who are continuously under the escort of trained personnel. CAs are established in accordance with the WIPP Radiation Safety Manual and are managed to limit the radiation exposure to personnel to less than 100 millirem per year. The CA is initially set at the entrances to the Parking Area Container Storage Unit (Parking Area Unit), Waste Handling Building Container Storage Unit (WHB Unit) Bay, and portions of the underground. The boundary of the CA is posted with signs as specified by the Permittees.

Waste Isolation Pilot Plant Hazardous Waste Permit October 16, 2006

- 12-hour shift. Whenever scheduled security patrols cannot be made, for situations such as
- inclement weather or an emergency, the reason for missing the patrol will be documented in the
- security logbook. In addition to the security officers, WIPP facility employees are called upon to
- challenge any person in the WIPP facility who is not wearing a badge or who is not under escort
- when an escort is required. Further physical protection is provided by fences, protective lighting,
- 6 and locked buildings.
- 7 C-1a(2) Barrier and Means to Control Entry
- 8 The existence of a barrier and a means to control entry demonstrates compliance with
- 20.4.1.500 NMAC (incorporating 40 CFR §264.14(b)(2)). Each is discussed in detail in the
- following sections.
- 11 C-1a(2)(a) <u>Barrier</u>
- The surface portion of the WIPP facility PPA is contained within a 35 acre (14 hectare) fenced
- area. This area is surrounded by a permanent 7 foot (ft) (2.13 meter [m]) high chain-link fence
- that is topped by three strands of barbed wire, for a total height of 8 ft (2.44 m). The fence
- encloses major surface structures. The regularly inspected chain-link fencing at the WIPP
- facility completely surrounds the active portion of the facility, thereby complying with 20.4.1.500
- NMAC (incorporating 40 CFR §264.14(b)(2)(i)). Access is normally through the Main Gate on
- the west side of the PPA. Two other gates are available for emergency use. One of these gates
- is opened to allow salt trucks access to the salt pile. Use of all gates is under the supervision of
- 20 **security**.
- 21 C-1a(2)(b) Means to Control Entry
- 22 Entry into the PPA, whether by personnel or vehicles, is through controlled gates and doors.
- 23 WIPP-facility access-control procedures are designed to ensure that only properly identified and
- authorized persons, vehicles, and property are allowed entrance to and exit from the facility. A
- personnel identification and access control system is maintained within the facility. Employees
- identify themselves with an identification badge when entering or leaving the premises. Security
- officers require visitors to show proper authorization prior to allowing them to enter the facility. In
- addition, visitors are required to wear a temporary badge and may require an authorized escort.
- Because the WIPP facility controls entry to the active portion of the facility at all times, the
- requirements of 20.4.1.500 NMAC (incorporating 40 CFR §264.14(b)(2)(ii)), are met.
- For the purposes of entry control to areas where wastes are being handled, the Waste Handling
- Building Container Storage Unit (WHB Unit), the boundaries of the Parking Area Unit south of
- the WHB, and those portions of the underground where wastes are disposed are posted as
- Controlled Areas (CAs). The WIPP allows access to a CA by anyone who has successfully
- completed General Employee Radiological Training, which is included in the General Employee
- Training Course. Access for visitors can also be arranged with proper training.
- Areas within the CA, however, may have further access restricted. Smaller areas may be
- designated as Radiological Buffer Areas, Radiation Areas, and Radioactive Materials Area.
- These smaller areas are generally within the direct vicinity of waste handling activities or waste
- storage or disposal areas. They are sized and posted in accordance with strict guidelines.
- Activities in these areas are performed under a Radiological Work Permit (**RWP**), and personnel

- must be listed on the RWP before they are allowed to enter. To be listed on the RWP, personnel
- 2 must have the appropriate radiological and hazardous waste worker training and must have
- available radiation dose for the task. In addition, the individuals must sign the RWP
- acknowledging that they intend to comply with the radiological controls that are in place.
- 5 Personnel may be escorted into the smaller areas if they are escorted by a person who meets
- all of the above requirements and is not performing any work in the area.
- 7 The WHB Unit, the Parking Area Unit, and the underground Hazardous Waste Disposal Units
- 8 (HWDUs) will be posted with a sign that states: "Danger: Authorized Personnel Only" in both
- 9 English and Spanish.
- 10 C-1a(3) Warning Signs
- The permanent chain-link fence surrounding the PPA is posted at approximately 50 ft (15.24 m)
- intervals with "No Trespassing" signs and with "Danger: Authorized Personnel Only" signs in
- English and Spanish. The signs are legible from a distance of 25 ft (7.62 m) and can be seen
- from any approach to the facility. These same signs, plus security and traffic signs, are also
- located on the controlled gates. The fence and gate signs at the WIPP facility fully comply with
- 20.4.1.500 NMAC (incorporating 40 CFR §264.14(c)). Warning signs with "Controlled Area" and
- "Hazardous Waste Management Unit" will be posted at entrances to the HWDUs prior to the
- emplacement of waste.